



Notes :

- 1) n is the no. of units connected on RS-485 bus, which should not be more than 32. If more than 32 units are required to be connected, then use RS-485 repeater. Each repeater allows 32 units load.
- 2) It is recommend to use shielded twisted pair cable for RS-485 bus and only one side of the shield should be earthed.
- 3) Typical value of Terminating Resistor is 120 ohm.
- 4) For other wiring details of TPR-501 please refer to ANNEXURE 2.

Winding Temperature Scanner TPR-501-C / TPR-501-RC Typical Loop Diagram of RS-485		Date	Dim.	Scale
		12/08/17	-	N.T.S
ANNEXURE - 4				